

Contents


Plastic case

(External dimensions 600 x 510 x 310 mm):

- 4 pcs. Y-cable DZCY
- 1 pc. display box DDBF 4-SC incl. software InspectMaster
- 1 pc. power adapter (battery charger)
- · Manual for DSRV, DDBF
- 4 strain clamp ø 30 100 mm
- 4 strain clamp ø 100 170 mm



Ideal for machine adjustment of electric and hydraulic machines





Description

Portable 4-channel system for strain measurement on tie bars and shafts. The strain clamps are mounted on the measurement object. The display box shows the measured strain of the four sensors in μe (strain unit), t or kN. The average value is also displayed.


Depending on the position of the sensor on the tie bar for example the parallelism or the clamp force of presses, injection mo lding or diecasting machines can be analysed.

This set is ideal for machine setter and maintenance people. For casual machine setting and general monitoring with tie bar diameters from 30 up to 170 mm.

Order code

DSRV SET-MED-170

Measuring chain



With strain clamps ø 170 up to 240 mm upgradable.

Pos.	Pcs.	Article	Description	Technical data
1	4	DSRV	Strain clamp	page 7.12
2	4	DZCY	Y-cable	page 7.14
3	1	DDBF	Display box incl. power adapter	page 9.6
			moi: povvoi adaptoi	page o.o

7.6 www.baumer.com